Baylor 6032 Brake





Baylor 6032 Elmagco Brake has been completely overhauled. All new coils and the brake has been subjected to Magnetic Particle inspection. All fits and tolerances have been checked and a complete data book from our third party brake rebuilder is included. Condition: Rebuilt.

Rating: Not Rated Yet
Ask a question about this product

ManufacturerBaylor